


## Cobber Staple Ordering Guide

A) Edge 6 staples per meter



For a typical installation:

### Order 4 Staples per Square Meter

Example:

1000 square meters of material:

4 staples per sqr meter = 4000 staples

Typical ordering formula:

- |                          |                                   |
|--------------------------|-----------------------------------|
| A) Staple for edges:     | 6 per meter                       |
| B) Edges alternate:      | 2 staggered rows of 5 staple each |
| C) Staples for overlaps: | 6 per meter                       |
| D) Staples for infills:  | 3 per meter square                |

Note: Refer to design or engineer specifications for your specific requirements

It's always safer to put a few extra staples in, then to reintsall the job or have your reputation damaged.